

## Therma-Hygrometer

with comfort level indicator

- Displays both humidity & temperature
- Max/min memory function

This new therma-hygrometer displays both the humidity and temperature in addition to indicating and recording the maximum and minimum readings. The unit features an analog arrow indicator and a colour-coded bar to display humidity comfort levels e.g. dry, comfort or wet.

The instrument measures both humidity and temperature over the range of 0 to 50 °C and 10 to 99 %rh utilising the internal sensors. The therma-hygrometer is ideal for monitoring both temperature and humidity in rooms, offices, factories and similar to ensure optimum working conditions are maintained.

The unit is housed in an ABS case, measuring 20 x 100 x 110 mm, that incorporates a useful foldaway stand and a keyhole slot for hanging on a wall.

Order Code	Description
810-130	Therma-hygrometer - comfort



Specification	Temperature	Humidity
Range	0 to 50 °C	10 to 99 %rh
Resolution	0.1 °C/°F	1 %rh
Accuracy	±1 °C	±5 %rh
Battery	2 x 1.5 volt AAA	
Battery life	10000 hours	
Display	Dual custom LCD	
Dimensions	20 x 100 x 110 mm	
Weight	150 Grams	

## Therma-Hygrometer

max/min & alarm functions

- Range of -49.9 to 69.9 °C & 20 to 99 %rh
- Integral %rh & remote temperature probe

This therma-hygrometer simultaneously displays both the humidity and temperature in addition to indicating and recording the maximum and minimum readings.

The instrument measures both humidity and temperature over the range of 0 to 49.9 °C and 20 to 99 %rh utilising the internal sensors. Utilising the external temperature sensor the temperature range is extended to -49.9 to 69.9 °C.

The unit features a temperature alert alarm that will sound when the external remote temperature probe indicates the temperature is 0 °C or below. This feature is ideal for frost/freeze alert in horticulture and similar.

The unit is housed in an ABS case, measuring 20 x 65 x 97 mm, that incorporates a useful foldaway stand and a keyhole slot for hanging on a wall.

Order Code	Description
810-155	Therma-hygrometer - alarm



Specification	Temperature	Humidity
Range	-49.9 to 69.9 °C	20 to 99 %rh
Resolution	0.1 °C/°F	1 %rh
Accuracy	±1 °C	±5 %rh
Battery	1.5 volt AAA	
Battery life	10,000 hours	
Display	Dual custom LCD	
Dimensions	20 x 65 x 97 mm	
Weight	100 Grams	